

Wescom Signal & Rescue UK Ltd. Wilne Mill, Draycott, Derby DE72 3QJ, United Kingdom Tel: +44 (0) 1332 871 100 www.wescom-group.com

PACKING SPECIFICATION

PAGE 1 OF 2

PS100-110 ISSUE 5

PRODUCT INFORMATION

Product Description	Comet Orange Smoke Signal / PW Lifesmoke Mk9/Aurora Lifesmoke
Part Number	9192000 / 9537000 / 9537020 (BAM-P1-0191)
Maximum Quantity Per Box	24
Dimensions	37 x 27 x 27cm
Estimated Gross Weight	9.4kgs
Estimated Net Weight	8.9kgs
Net Explosive Content Per Item	0.239kgs
UN Packing Instruction	P135
Hazard Class	1.4S
UN Number	UN0507
Propper Shipping Name	Signals, Smoke
Tunnel Restriction Code	E
Shipping Method	Roadfreight, Seafreight & Passenger/Cargo Aircraft
Box Marking	4G/Y22/S/**/D/BAM5391-KW-HL

PACKING MATERIALS

1.	1 x UN Approved Fibreboard Box, Part No 50004106800
2.	Corrugated cardboard grate and sheets as required

- 3. 50mm Vinyl adhesive tape as required
- 4. 1 x Hazard warning label 1.4S

PACKING METHOD

1.	Assemble the fibreboard box (picture 1) and place one of the cardboard sheets in the bottom of the box.
2.	Insert cardboard grate. Fill the box with smoke signals, vertically stacked, in two layers à 24 pieces (picture 2)
3.	Fill the space between the smoke signals and the lid with cardboard sheets in order to prevent them from moving in the box (picture 3).
4.	Close and seal the box with the adhesive tape, ensuring that the tape overlaps the edges of the box by at least 100mm (picture 4).
5.	Mark the box in accordance with UN transport of dangerous goods regulations (picture 5).



Wescom Signal & Rescue UK Ltd. Wilne Mill, Draycott, Derby DE72 3QJ, United Kingdom Tel: +44 (0) 1332 871 100 www.wescom-group.com

PACKING SPECIFICATION

PAGE 2 OF 2

PS100-110 ISSUE 5

PACKING METHOD PICTURES 1-5

PICTURE 1.



PICTURE 3.



PICTURE 5.



PICTURE 2.



PICTURE 4.

